MSDS Material Safety Data Sheet
Blended Waxes, Inc.

Dip Seal

MSDS Number: 049 Revision Date: 4/1/09

1 PRODUCT AND COMPANY IDENTIFICATION

Manufacturer

Blended Waxes, Inc.
1512 S. Main Street
P.O. Box 3044
Oshkosh, WI 54902

Contact: Lab
Telephone Number: (920) 236-8080
FAX Number: (920) 236-8081
E-Mail: NA
Web www.blendedwaxes.com

Product Name:	Dip Seal
Revision Date:	4/1/09
MSDS Number:	049
Common Name:	Paraffin Wax
CAS Number:	8002742
Product Use:	An over-dip wax for sealing voids and cracks in runners and sprues.

2 HAZARDS IDENTIFICATION

Route of Entry:	Mouth, Skin
Target Organs:	NA
Inhalation:	Yes
Skin Contact:	Yes
Eye Contact:	No
Ingestion:	No

NFPA-ratings (scale 0-4): Health = 1, Fire = 1, Reactivity = 0

3 COMPOSITION/INFORMATION ON INGREDIENTS

Ingredients:

Cas #	Perc.	Chemical Name
8002742		Paraffin wax fume

4 FIRST AID MEASURES

Inhalation: Mild respiratory irritation or discomfort. Move affected person to fresh air.
Skin Contact: Flush with cold water, seek medical attention.
Eye Contact: Yes, when product is molten
Ingestion: NA

5 FIRE FIGHTING MEASURES

Flash Point: 415 F
Flash Point Method: C.O.C.
LEL: NA
UEL: NA
Flammability Classification: NA

6 ACCIDENTAL RELEASE MEASURES

Dike or contain molten material. Allow material to solidify, then scrape up solid material. Handle as solid waste clean up. Clean up solid spills to prevent slippery surface conditions.

7 HANDLING AND STORAGE

Handling Precautions: NA
Storage Requirements: Store in cool, dry area away from heat or direct sunlight.

8 EXPOSURE CONTROLS/PERSONAL PROTECTION

Engineering Controls: NA
Protective Equipment: HMIS PP, B | Goggles, Gloves
Exposure Guidelines/Other: Provide adequate ventilation to prevent build up of fumes.

9 PHYSICAL AND CHEMICAL PROPERTIES

Appearance:	Red, waxy		
Physical State:	Solid	**Boiling Point:**	NA
Odor:	Resin-like odor	**Freezing/Melting Pt.:**	119 F - 145 F
pH:		**Solubility:**	Nil <0.1%
Vapor Pressure:	<0.1	**Spec Grav./Density:**	<.84
Vapor Density:	NA		

Evap. Rate: NA

10 STABILITY AND REACTIVITY

Stability:	Stable
Conditions to avoid:	Avoid heating above 300 F to prevent build up of fumes.
Materials to avoid (incompatability):	Strong oxidizing agents
Hazardous Decomposition products:	CO, CO2 and unidentified organic compounds are byproducts of combustion.
Hazardous Polymerization:	Will not occur.

11 TOXICOLOGICAL INFORMATION

12 ECOLOGICAL INFORMATION

13 DISPOSAL CONSIDERATIONS

Incineration or burial in accordance with local, state and federal regualtions.

14 TRANSPORT INFORMATION

15 REGULATORY INFORMATION

```
COMPONENT / (CAS/PERC) / CODES
---------------------------------------------------------------
*Paraffin wax fume (8002742 n/a%) MASS, OSHAWAC, PA, TXAIR

REGULATORY KEY DESCRIPTIONS
---------------------------------------------------------------
MASS = MA Massachusetts Hazardous Substances List
OSHAWAC = OSHA Workplace Air Contaminants
PA = PA Right-To-Know List of Hazardous Substances
TXAIR = TX Air Contaminants with Health Effects Screening Level
```

16 OTHER INFORMATION

END OF MSDS DOCUMENT